

# MCS Preventative measures for the Parade







Heras fencing removed and ranch boarding installed

# MCS Preventative measures for the Parade



Before





## MCS Preventative measures for the Parade

Ladder hatches locked off and boards installed



Walkways boarded off to prevent access around the scaffold

# MCS Preventative measures for the Parade

Entrance doors to  
hoarding boarded at  
base of scaffold

# MCS Preventative measures for the Parade





# MCS Preventative measures for the Parade


Potential climbing areas to scaffold have been ranch boarded



MILLANE



MILLANE



# MCS Preventative measures for the Parade

- Scaffold to the front elevation has been cleaned and all materials have been removed; additional scaffold ties have been added to the front and side elevation.